


# SL56 35A-60200 SERVICE LETTER

1.	Release Date: 08/22/2022				
2.	Service Letter No.: SL56 35A-60200 Rev I/R				
3.	Subject: Bi-Directional Hydraulic Electric Pump and Hydraulic Intake Pipe				
4.	Part/Assembly No.: 35A-60200 and 35A-60235				
5.	5. Float Model (s) Affected: 3400 Aerocet Floats				
6.	Compliance: ☐ Mandatory ☑ Recommended ☐ Optional				
7.	Approval: All information provided is in accordance with approved data.				
8.	Corrective Action: Non-required.				
9.	<b>Time Required:</b> Approximately 1.5 hrs. not including lifting of the aircraft, bleeding the system and completing gear swings.				
10.	Payments: ☐ Credit to Customer ☐ Under Warranty ☒ Customer Pays				
11.	Call Parts Department (208) 448-0400 for Parts Kit				

A retaining ring and safety wire has been added to improve suction screen installation on the hydraulic pump. Additionally, a snap ring groove to the hydraulic intake pipe was added to create a hard stop for the suction screen to seat against.




## **Hydraulic Electric Pump Exploded View, Simplified**



### 35A-60235 HYDRAULIC INTAKE PIPE

ADDED snap ring groove to hydraulic intake pipe to create a hard stop for the suction screen to seat against. Part may be available for purchase from Aerocet, or, optionally, groove may be added as shown below.



Parts List for SL56				
QTY	Part Number	Description	Comments/Alternates	
1	35A-60235	INTAKE PIPE	*OR MODIFY EXISTING WITH GROOVE SHOWN ABOVE	
1	MS16624-1066	RETAINING RING		
1	MS20995C20	SAFETY WIRE		



# **Examples of Attachment Techniques**

### 35A-60200 Sheet 8

