

SERVICE LETTER SL39 66-47050

1. **Release Date:** 01/03/2018
2. **Service Letter No.:** SL39 66-47050
3. **Reason for Change:** Hand Pump Poly Pak Seals
4. **Part/Assembly No.:** 66-47050
5. **Float Model Affected:** 6650
6. **Disposition of Product in Field:** Informational Only.
7. **Approval:** All information provided is in accordance with approved data.
8. **Corrective Action:** Non-required.
9. **Time Required:** NA
10. **Payments to Customer:** NA

Notes:

Hand pump assemblies were built with “quad” shaped Polypak seals instead of “O” shaped Polypak seals. This is not to type design. It was determined after testing that the quad seals work equally as well as the “O” rings. Engineering, with DER approval, has changed the drawing to show both seals available for assembly.

Rev	Date	Summary of Change	Authorized by
I/R	01/03/2018	Initial Release	LM

-END-