

**Service Letter #:** SL06-36-70008

**Date:** 08/05/13


**Part/Assembly #:** 36-70008/Supplemental Airplane Flight Manual (SAFM) A-10011 – all previous.

**Float Model Affected:** Aerocet Model 3500 and 3500L on Cessna 206 Aircraft (STC SA00003SE) (All before 8/1/13)

**Symptom:** Typographical Error on Aerocet supplied placard: light, forward CG may be incorrect. Flight Manual Supplement A-10011 has correct limitations.

**Approval:** This SL reflects FAA Approved design changes and does not require FAA approval.

**Corrective Action:** Please check your installation against the SAFM. Replacement placards are available through Aerocet or you can correct your existing placard by any permanent means.



**Figure 1 Showing correct verbiage from SAFM**

**Tools Needed:** None.

**Materials Needed:** None

**END -**