

Service Letter #: SL06-36-70008

Date: 08/05/13

Part/Assembly #: 36-70008/Supplemental Airplane Flight Manual (SAFM) A-10011 – all previous.

Float Model Affected: Aerocet Model 3500 and 3500L on Cessna 206 Aircraft (STC SA00003SE) (All before 8/1/13)

Symptom: Typographical Error on Aerocet supplied placard: light, forward CG may be incorrect. Flight Manual Supplement A-10011 has correct limitations.

Approval: This SL reflects FAA Approved design changes and does not require FAA approval.

Corrective Action: Please check your installation against the SAFM. Replacement placards are available through Aerocet or you can correct your existing placard by any permanent means.




Figure 1 Showing correct verbiage from SAFM

Tools Needed: None.

Materials Needed: None

END -