

**SERVICE LETTER SL36 66-47120**

1. **Release Date:** 08/11/2017
2. **Service Letter No.:** SL36 66-47120
3. **Reason for Change:** Potential non-conforming selector valve in the hydraulic float pedestal.
4. **Part/Assembly No.:** 66-47120
5. **Float Model Affected:** 6650
6. **Disposition of Product in Field:** Informational Only
7. **Approval:** All information provided is in accordance with approved data.
8. **Corrective Action:** None
9. **Time Required:** 1 Hour
10. **Payments to Customer:** None. Call (208) 448-0400 for Parts Department

**Notes:**

Aerocet, Inc. has become aware of a non-conforming selector valve in the hydraulic float pedestal, 66-47200. The potential non-conforming valve may have resulted in the installer switching hydraulic lines in the aircraft to ensure the proper gear operation. The risk is that a future replacement float pedestal will not operate in the correct direction until the hydraulic lines are corrected. To determine whether you have a conforming or a non-conforming selector valve, trace the hydraulic lines in accordance with Drawing #66-12700, Rev H or later for approved version.

-END-